AUTODOC CLUB

How to change pollen filter on **Honda Insight ZE2_ZE3** – replacement guide





VIDEO TUTORIAL



Important!

This replacement procedure can be used for:
HONDA Jazz III Hatchback (GE_, GG_, GP_, ZA_) 1.3 HYBRID (GP1), HONDA Jazz III Hatchback (GE_, GG_, GP_, ZA_) 1.4, HONDA Jazz III Hatchback (GE_, GG_, GP_, ZA_) 1.3 i, HONDA Jazz III Hatchback (GE_, GG_, GP_, ZA_) 1.2, HONDA INSIGHT (ZE_) 1.3 Hybrid (ZE28, ZE2), HONDA CITY Saloon (GM) 1.4 i-V TEC, HONDA Jazz III Hatchback (GE_, GG_, GP_, ZA_) 1.5 i-VTEC, HONDA CITY Saloon (GM) 1.5 i-VTEC (GM26), HONDA CITY Saloon (GM) 1.5 Flex, HONDA Jazz III Hatchback (GE_, GG_, GP_, ZA_) 1.5 Flex, HONDA CR-Z (ZF) 1.5 Hybrid, HONDA City Saloon (GM4, GM5, GM6, GM9) 1.5 i-VTEC, HONDA HR-V (RU) 1.8, HONDA HR-V (RU) 1.6 i-DTEC (RU8), HONDA HR-V (RU) 1.5 (RU1), (+ 29)

The steps may slightly vary depending on the car design.





Replacement: pollen filter – Honda Insight ZE2_ZE3. Professionals recommend:

- Replace the cabin filter at least once every six months, in early spring and autumn seasons.
- Follow the terms, recommendations and requirements of the part operation provided by the manufacturer.
- If the air flow into the cabin has sharply reduced, replace the filter before a scheduled maintenance.
- Please note: all work on the car – Honda Insight ZE2_ZE3 – should be done with the engine switched off.

CARRY OUT REPLACEMENT IN THE FOLLOWING ORDER:

1 Open the glove box.



2 Detach the stopper (strap) from the glove box lid.








3 Release the cabin filter cover clips. Remove the cabin filter housing cover.



4 Remove the cabin filter.



Replacement: pollen filter – Honda Insight ZE2_ZE3. AUTODOC recommends:

- Do not attempt to clean and reuse the filter - it will affect the quality of air cleaning inside the car.

5 Install a new cabin filter according to the mark.








AUTODOC recommends:

- Replacement: pollen filter – Honda Insight ZE2_ZE3. Be sure to position the filtering element correctly. Avoid misalignment.
- Follow the air flow direction arrow on the filter.


6 Reinstall the cabin filter housing cover. Make sure you hear a click indicating that it is locked in place.



7 Attach the stopper (strap) to the glove box lid.




8 Close the glove box.









9 Switch on the ignition.



10 Switch on the air conditioning system. This is necessary in order to make sure that the component operates properly.



11 Switch off the ignition.






VIEW MORE TUTORIALS



AUTODOC — TOP QUALITY AND AFFORDABLE CAR PARTS ONLINE



A GREAT SELECTION OF SPARE PARTS FOR YOUR CAR

BUY SPARE PARTS FOR HONDA

POLLEN FILTER: A WIDE SELECTION





CHOOSE CAR PARTS FOR HONDA INSIGHT ZE2_ZE3

POLLEN FILTER FOR HONDA: BUY NOW

POLLEN FILTER FOR HONDA INSIGHT ZE2_ZE3: THE BEST DEALS & OFFERS

DISCLAIMER:

The document contains only general recommendations that may be useful for you when you perform repair or replacement work. AUTODOC shall not be liable for any loss, injury, damage of property occurring in the repair or replacement process due to incorrect use or misinterpretation of the provided information.

AUTODOC shall not be liable for any possible mistakes and uncertainties in this guide. The information provided is for information purposes only and cannot replace advice from specialists.

AUTODOC shall not be liable for incorrect or hazardous usage of equipment, tools and car parts. AUTODOC strongly recommends to be careful and observe the safety rules when performing repair or replacement works. Remember: usage of low quality auto parts does not guarantee you the appropriate level of road safety.